


Touch Point Sensor





Edge Finder with Beeper & Optical

- No need to rotate while measuring.
- The red light was sealed with setting red-glue; it can concentrate the light and resist water.
- The sensor beeps while the red light is on.
- The sensor will beep when the user couldn't see the reverse side or get a
- Example. If sensor's light is working, visually you couldn't see inside of the inner hole, while probing the user can be warned by the beeper.
- When probe the deep hole, you can't see the red light, but you can hear the sound from beeper. **Batteries**
- used:UM5#,12V*1PCS Accuracy: within ±0.005mm.



OPTICAL TYPE WITH BEEPER

Unit:mm

ORDER NO.	D	d1	d2	L	11	12	BATTERY TYPE	WEIGHT (kg)	CODE NO.
VPS-20B	Ø20	18	10	157	77	41	UM-5#(SP)	0.4	3402-001
VPS-32B	Ø32	18	10	157	74	41	x1PCS/12V	0.7	3402-002



Touch Point Sensor

Optical Type

High sensitivity position sensor.

With Out Beeper

- Red pilot can be seen clearly.
- Whole travel of red pilot is sparkling, detecting also can be done during turning while spindle stops.
- Location of end surface, outter circle dia., inner circle dia. of the workpiece for processing can be detected with full effect.
- Deviced with safety line excess, ball supported by spring, so even line excess, it will be separtated easily from the base shown as the fig.
- The precision will reach up to micrometer while the ball returns to center position.
- d1 Edge Finder
 - Accuracy:Within ±0.005mm

OPTICAL TYPE

Unit:mm

ORDER NO.	D	d1	d2	L	11	12	BATTERY TYPE	WEIGHT (kg)	CODE NO.
VPS-20	20	18	10	157	76	33		0.4	3402-003
VPS-32	32	18	10	157	74	41	UM-5#(SP) x2P/R1/1.5V	0.7	3402-004
VPS-20-3/4	3/4	18	10	157	76	33		0.4	3402-011

After Reading the Following instruction, please use touch point sensor correctly due to it's a highly sensitive position detector. Don't Rotate the touch point sensor while using it.

1.Install BATTERY

VPS-20


Take off the screw cover and insert batteries correctly. Do not insert batteries upside down.


VPS-32

2.CONFIRMATION OF LIGHTING CHECK the lighting of red lamp by touching A-B part with a metal (clip,L-PLATE etc.)

3.MEASURING METHOD

As soon as the ball (outside dia. 10mmø)touches the work piece with the main spindle stopped, The red lamp lights on.











請注意/光雷式尋邊器不適合迴轉使用 Notice: optical edge finder is not suited FOR Rotation.




Touch Point Sensor



Edge Finder



VPS-201



This series is a high precision setting device for positioning the accurate center between tool spindle of machine and reference surface of working at low-cost and saving time.

Accuracy: within ±0.005 mm

Made of tool steel, hardened and ground.

Suitable rotation speed: VPS-201 450 to 600rpm.

VPS-401 600 to 1,000 rpm




CREAMIC TYPE VPS-201C




MECHANICAL TYPE

ORDER NO.	VPS-201	VPS-201C		
WEIGHT (KG)	0.03	0.06		
CODE NO.	3402-005	3402-007		









Touch Point Sensor

Deluxe Type




FEATURES:


- Material: high-carbon steel.
- Accuracy: within ±0.003mm
- Hardness: HRC 58°± 1°
- R.P.M. Within 600-1000
- Suitable for milling machine. Drill machine and boring machine.
- Edge Finder


VPS-401 (2 PCS/SET) VPS-402A(LONG) SINGLE VPS-402B(SHORT) SINGLE

ORDER NO.	VPS-401	VPS-401C		
PCS/SET	2PCS/SET	2PCS/SET		
MATERIAL	STEEL	CERAMIC		
WEIGHT (KG)	0.26	0.26		
CODE NO.	3402-006	3402-008		



STEEL








Touch Point Sensor



MECHANICAL TYPE




VPS-301 STEEL **VPS-301S STAINLESS**






VPS-302 STEEL **VPS-302S STAINLESS**






VPS-301C CERAMIC TYPE








VPS-302C CERAMIC TYPE









VPS-303 NON-MAGNETIC COATING






Spindle runs about 500rpm, move spindle closed to measuring surface.



When measuring probe touches workpiece, it looks in one part.



When the probe and shank are in alignment, probe will slide out of rotating center Now,the center spindle is located 5mm away from measuring surface

- Accuracy of zero point to point is within ± 0.003mm
- R.P.M. within 450-600.
- Max. flange can be clear your sight sense.
- MIN.(4mm) can be test mini hole for your workpiece.

ORDER NO.	MATERIAL	HARDNESS	WEIGHT (kg)	CODE NO.
VPS-301	ALLOY	HRC 56°	0.06	3402-100
VPS-302	STEEL	HKC 36	0.05	3402-101
VPS-301S	STAINLESS	HRC 60°	0.06	3402-102
VPS-302S	STAINLESS	HRC 60	0.06	3402-103
VPS-301C	CERAMIC	HRC 60°	0.06	3402-104
VPS-302C	CERAMIC	HRC 60°	0.06	3402-105
VPS-303	NON-Magnetic Coating	HRC 56°	0.06	3402-106